

Cutting and Welding

Permits for Cutting and Welding Operations are required for any and all welding, cutting, open torches and hot work operations.

Conditions of this permit are as follows:

- May require an inspection
- Must have a designated hot works area
- Must have a permit for the compressed gas cylinder
- No combustibles in work area
- Openings in floors, walls, ducts or shafts shall be tightly covered
- Fire watch required and person must be trained on how to use the fire extinguisher
- Fire extinguisher required
- Must check area after cutting and welding is complete

During the application process be prepared to download the following documents: 1) Copy of Fire Extinguisher tag